

VEHICLE INSPECTION REPORT

PE65VDZ

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	29/10/2015	VIN	XLRAEL1500L448650	Gearbox	MANUAL
Year	2015	Body Style	Box Van	Axle Combi	4x2
Mileage	458,625 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	DIESEL	Service documents	Printout	Tail Lift	Cantilever
GVW	7500kg	MOT Due	30/09/2026		
Colour	RED	Cab Type	DAY CAB		



Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Dented
With Paint Damage

2: Bonnet
Chipped
Multiple Chips




3: Panel Front
Scratched
Over 25mm Thru Paint

4: Bumper Front
Dented
With Paint Damage



5: Door Mirror Assy nsf
Broken
Replace

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Door osf
Dented
Over 30mm

8: Door osf
Scratched
Over 25mm Thru Paint



9: Carpets Front
Torn
Over 10mm

10: Door Pad osf
Soiled
Heavy



11: Seat Base Cover osf
Torn
Over 3mm

12: Seat Base Cover nsf
Torn
Over 3mm



13: Fascia Panel
Missing
Replace

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		