

# VEHICLE INSPECTION REPORT

**YN70ZWF**

## Fiat Ducato 2.3 MULTIJET 160PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Buyer To Apply

### Details

Reg. date	02/09/2020	VIN	ZFA25000002P04707	CAP Below	£4,325.00
Year	2020	Body Style	Recovery	Gearbox	MANUAL
Mileage	71,432 Miles Not Warranted	MOT Due	11/06/2025	Gears	6
Fuel Type	Diesel	CAP Clean	£5,875.00		
Colour	BLUE	CAP Average	£5,275.00		

\*WARNING LIGHT ON DASH, ENGINE ISSUES\* WINCH, MANUAL RAMPS, E/MIRRORS

### Tyres

NSF

NSR

OSF

OSR

Spare


## Features

- Air conditioning
- Front electric windows

## Photos










## Condition Check



## Damage Photos



1: Wing osf  
Dented  
With Paint Damage



2: Front TowEye Cvr  
Missing  
Replace



3: Bonnet  
Chipped  
Multiple Chips



4: Screen Front  
Chipped  
Over 10mm



5: Bumper Rear  
Dented  
Over 30mm



6: General Exterior  
Soiled  
Light



7: Door osf  
Scratched  
Over 25mm Thru Paint



8: Carpets Front  
Holed  
Over 3mm

## Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	Fault		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK