

VEHICLE INSPECTION REPORT

FD17XTY

Daf XF 480

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 13/07/2017

Year 2017

Mileage 839,268 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRTGH4300G165802

Body Style Tractor Unit

MOT Due 31/08/2025

Cab Type SUPER SPACE CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lif Steert

Rear Suspension Air

SLIDING 5TH WHEEL

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Radio/CD
- Cloth seat trim
- Cruise control
- Air conditioning
- Navigation system
- Front electric windows
- Park assist camera
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front
Dented
With Paint Damage



4: Wing nsf
Chipped
Multiple Chips



5: Door osf
Chipped
Multiple Chips



6: Screen Front
Cracked
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		