

VEHICLE INSPECTION REPORT

SA68WWH

DAF LF 180

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow

Details

Location	Livingston	Colour	WHITE	Axle Combi	4x2
Reg. date	09/11/2018	VIN	XLRAEL1500L479771	Rear Suspension	Steel
Year	2018	Body Style	Box Van	Rear Doors	Roller
Mileage	494,739 Km Not Warranted	MOT Due	31/08/2026	Tail Lift	Column
Fuel Type	DIESEL	Cab Type	DAY CAB		
GVW	7500kg	Gearbox	MANUAL		

WARNING LIGHTS ON DASH

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Radio/CD

Photos



