

VEHICLE INSPECTION REPORT

NX73YZP

IVECO S-WAY 530

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 25/01/2024

Year 2024

Mileage 154,628 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFS62NV70C523546

Body Style Tractor Unit

MOT Due 24/01/2027

Cab Type AS SLEEPER

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lif Steert

Rear Suspension Air

SLIDING 5TH WHEEL

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4


Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Navigation system
- Central locking
- Digital radio
- Cloth seat trim

Photos



Condition Check



Damage Photos



1: Bumper Front
Chipped
Multiple Chips



2: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



3: Screen Front
Scratched
Over 30mm

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour -

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		