

VEHICLE INSPECTION REPORT

YG65HAU

Ford Transit 350 2.2 TDCI 125PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 01/09/2015

Year 2015

Mileage 130,425 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0DXXTTGDFK01929

Body Style Dropside L2

MOT Due Expired

CAP Clean £3,650.00

CAP Average £2,975.00

CAP Below £2,150.00

Gearbox MANUAL

Gears 6

Tyres

NSF

NSR

OSF

OSR

Spare


Features

- Air conditioning
- Front electric windows

Photos



Condition Check



Damage Photos



1: Moulding on Wing
Scuffed (Unpainted)
Over 100mm



2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Screen Front
Chipped
Over 10mm



4: Bonnet
Chipped
Multiple Chips



5: Bumper Front
Scratched
Over 25mm Not Thru Paint



6: Fog Lamp Surrounds
Broken
Replace



7: Wing nsf
Dented
Over 30% Of Panel



8: Moulding nsf Wing
Broken
Replace



9: Door nsf
Dented
With Paint Damage



10: General Exterior
Soiled
Light



11: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



12: Bumper Rear
Rusted
Over 5mm



13: Door osf
Dented
With Paint Damage



14: Sill os
Rusted
Over 5mm



15: Carpets Front
Holed
Over 3mm



16: Seat Base Cover osf
Torn
Over 3mm



17: Other
N/A
N/A



18: Other
N/A
N/A



19: Other
N/A
N/A



20: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK