

VEHICLE INSPECTION REPORT

DN23WBD

Ford Transit Custom 300 2.0 ECOBLUE 130PS LIMITED

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 20/04/2023

Year 2023

Mileage 67,935 Miles Not Warranted

Fuel Type DIESEL

GVW 3000kg

Colour WHITE

VIN WF0YXXTTGYPC48965

Body Style Panel Van

MOT Due 04/05/2027

CAP Clean £12,200.00

CAP Average £11,350.00

CAP Below £9,750.00

Gearbox MANUAL

Gears 6

OUTSTANDING RECALL AD-BLUE, SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF


OSR



Spare

Features


- Front parking sensor
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5

2: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint



3: Qtr Panel osr
 Scratched
 Over 25mm Not Thru Paint

4: Qtr Panel osr
 Scratched
 UpTo 25mm Thru Paint

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	