

VEHICLE INSPECTION REPORT

FL69XBJ

Vauxhall Vivaro 2900 1.5D 100PS EDITION

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Doncaster

Reg. date 31/10/2019

Year 2019

Mileage 70,915 Miles
Warranted

Fuel Type DIESEL

GVW 2830kg

Colour WHITE

VIN VXEVBYHRKL7005054

Body Style Panel Van L1

MOT Due 15/07/2027

CAP Clean £6,250.00

CAP Average £5,400.00

CAP Below £4,150.00

Gearbox MANUAL

Gears 6

INTERMITTENT DPF, LIMP MODE FAULT AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS, RACKING IN REAR, DEADLOCKS

Tyres

NSF

NSR

OSF

OSR




Spare

Features

- Bluetooth connection
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Cruise control
- Auxiliary input socket
- Drivers airbag
- Front parking sensor
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



3: Qtr Panel nsr
Dented
With Paint Damage

4: Qtr Panel nsr
Dented
With Paint Damage



5: Lamp nsr
Broken
Replace

6: Wing osf
Chipped
Multiple Chips



7: Door Mirror Assy osf
Broken
Replace

8: Screen Front
Chipped
UpTo 10mm



9: Carpets Front
 Holed
 Over 3mm

10: Seat Base Cover nsf
 Soiled
 Heavy

Interior

Carpet Condition		Poor	Upholstery Condition		OK
Seat Condition		Poor	Odour		No
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			