

VEHICLE INSPECTION REPORT

YF66UWB

Ford Transit Connect 220 1.5 TDCI 75PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 24/01/2017

Year 2017

Mileage 105,145 Miles
Warranted

Fuel Type DIESEL

GVW 2215kg

Colour WHITE

VIN WF0RXXWPGRGY84629

Body Style Panel Van L1

MOT Due 03/08/2027

CAP Clean £2,600.00

CAP Average £2,175.00

CAP Below £1,600.00

Gearbox MANUAL

Gears 5

SIDE LOAD DOOR, DEADLOCKS, RACKING IN REAR

Tyres

NSF

NSR

OSF


OSR





Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Front parking sensor
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Qtr Panel nsr
Dented
With Paint Damage



3: Qtr Panel nsr
Dented
With Paint Damage

4: Qtr Panel nsr
Dented
With Paint Damage



5: Qtr Panel nsr
Dented
With Paint Damage

6: Qtr Panel osr
Dented
Over 30mm



7: Qtr Panel osr
Dented
Over 30mm

8: Door osf
Dented
Over 30% Of Panel



9: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		