

VEHICLE INSPECTION REPORT

LX65BBF

Mercedes-Benz SPRINTER 513 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Bedford

Fuel Type DIESEL

Body Style Minibus

Reg. date 22/01/2016

GVW 5000kg

MOT Due 21/01/2027

Year 2016

Colour WHITE

Gearbox AUTOMATIC

Mileage 150,568 Miles Not Warranted

VIN WDB9066552P217233

Tail Lift Tuckaway

WARNING LIGHTS ON DASH, MOT RECORDED IN KM & MILES 14 SEATS + DRIVER, TACHO 242321 KM, SIDE LOAD DOOR, LOLER INSPECTION REPORT PRESENT

Tyres

NSF

NSR

OSF


OSR






Spare

Features


- Park assist camera
- Rear parking sensor
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

2: A Post os
Rusted
Over 5mm




3: Bonnet
Chipped
Multiple Chips

4: Screen Front
Chipped
Over 10mm



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Wing nsf
Dented
Between 10mm + 30mm

8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Rusted
Over 5mm

10: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



11: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

12: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

14: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm



15: Qtr Panel osr
Rusted
Over 5mm

16: Sill os
Rusted
Over 5mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	Fault