

VEHICLE INSPECTION REPORT

PE63NJU

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 13/11/2013

VIN XLRAE45FF0L432616

Axle Combi 4x2

Year 2013

Body Style Box Van

Rear Suspension Steel

Mileage 990,365 Km Warranted

MOT Due 31/12/2025

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour RED

Gearbox MANUAL

*COLLECTED AS NON RUNNER - CORROSION**WARNING LIGHT ON DASH*

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features

- Cruise control
- Radio/CD
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front Grill
Broken
Replace



3: Bumper Front
Dented
With Paint Damage

4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint

6: Door osf
Dented
Over 30mm



7: Door osf
Scratched
Over 25mm Not Thru Paint

8: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		