

VEHICLE INSPECTION REPORT

FN73DBX

Renault Master Bloomfields Raceline 2.3DCI 145PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Bedford

Reg. date 07/12/2023

Year 2023

Mileage 44,780 Miles Not Warranted

Fuel Type DIESEL

GVW 3500kg

Colour CREAM

VIN VF6VF000970963504

Body Style Horsebox

Keys 2

MOT Due 06/12/2026

Gearbox MANUAL

REAR STORE, COOLING FAN, CAMERA TO HORSE AREA, SIDE LOADING, AD BLUE, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR



Spare

Features

- Air conditioning
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint

2: Bonnet
Chipped
Multiple Chips



3: Wing nsf
Dented
Between 10mm + 30mm

4: Door nsf
Chipped
1 To 5



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK