

VEHICLE INSPECTION REPORT

FP68KYS

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	32000kg	Cab Type	SLEEPER CAB
Reg. date	28/01/2019	Colour	WHITE	Gearbox	AUTOMATIC
Year	2019	VIN	XLRADM4100G242570	Axle Combi	8x4
Mileage	475,782 Km Warranted	Body Style	Tipper	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	31/01/2027		

MID-STEER, BULK BODY EDBRO TIPPING GEAR

Tyres






NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Bluetooth connection
- Cruise control
- Navigation system
- Park assist camera
- Auxiliary input socket
- Digital radio
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front
Dented
With Paint Damage

4: Wing nsf
Cracked
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		