

VEHICLE INSPECTION REPORT

FD680GW

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	32000kg	Cab Type	SLEEPER CAB
Reg. date	25/02/2019	Colour	WHITE	Gearbox	AUTOMATIC
Year	2019	VIN	XLRADM4100G244898	Axle Combi	8x4
Mileage	525,500 Km Warranted	Body Style	Tipper	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	28/02/2027		

WARNING LIGHTS ON DASH BULK BODY, EDBRO TIPPING GEAR, WEIGH SYSTEM, SHEETING SYSTEM

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Auxiliary input socket
- Front electric windows
- Cruise control
- Digital radio
- Central locking
- Navigation system
- Radio/CD
- Cloth seat trim
- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Door nsf
 Scratched
 Over 25mm Thru Paint

4: Wing nsf
 Cracked
 Replace



5: Door osf
 Scratched
 Over 25mm Thru Paint

6: Screen Front
 Chipped
 UpTo 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		