

VEHICLE INSPECTION REPORT

FN19EZC

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	32000kg	Cab Type	DAY CAB
Reg. date	06/03/2019	Colour	WHITE	Gearbox	AUTOMATIC
Year	2019	VIN	XLRADM4100G245906	Axle Combi	8x4
Mileage	503,042 Km Warranted	Body Style	Tipper	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	30/06/2027		

WARNING LIGHTS ON DASH EDBRO BULK TIPPING GEAR, SHEETING SYSTEM, WEIGH SYSTEM


Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Navigation system
- Park assist camera
- Auxiliary input socket
- Digital radio
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Door osf
Dented
With Paint Damage

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bonnet
Chipped
Multiple Chips

4: Panel Front
Cracked
Replace



5: Bumper Front
Scratched
Over 100mm Thru Paint

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Screen Front
Scratched
Over 30mm

8: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK		