

VEHICLE INSPECTION REPORT

FN19EWM

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	3500kg	Cab Type	DAY CAB
Reg. date	05/04/2019	Colour	WHITE	Gearbox	AUTOMATIC
Year	2019	VIN	XLRADM4100G244365	Axle Combi	8x4
Mileage	506,092 Km Warranted	Body Style	Tipper	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	30/04/2027		

EDBRO BULK TIPPING GEAR, SHEETING SYSTEM, WEIGH SYSTEM, SURROUND CAMERA SYSTEM

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Digital radio
- Cloth seat trim
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Auxiliary input socket
- Central locking


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint

2: Panel Front
Scratched
Over 25mm Thru Paint



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front Grill
Broken
Replace



5: Bumper Front
Scratched
Over 100mm Thru Paint



6: Panel Front
Scratched
Over 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint

Interior

8: Screen Front
Chipped
UpTo 10mm

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		