

# VEHICLE INSPECTION REPORT

**FP68KYE**

## DAF CF 450

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

|           |                      |            |                   |                 |           |
|-----------|----------------------|------------|-------------------|-----------------|-----------|
| Location  | Doncaster            | GVW        | 32000kg           | Cab Type        | DAY CAB   |
| Reg. date | 18/01/2019           | Colour     | WHITE             | Gearbox         | AUTOMATIC |
| Year      | 2019                 | VIN        | XLRADM4100G239179 | Axle Combi      | 8x4       |
| Mileage   | 380,634 Km Warranted | Body Style | Tipper            | Rear Suspension | Steel     |
| Fuel Type | DIESEL               | MOT Due    | 31/12/2026        |                 |           |

ALLOY BODY, EDBRO TIPPING GEAR, SHEETING SYSTEM, WEIGH SYSTEM

### Tyres

|       |      |      |      |      |
|-------|------|------|------|------|
| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
|       | OSO1 | OSO2 | OSO3 | OSO4 |



## Features

- Bluetooth connection
- Cruise control
- Navigation system
- Park assist camera
- Auxiliary input socket
- Digital radio
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim

## Photos












## Condition Check



## Damage Photos



1: Panel Front  
Cracked  
Replace

2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Bumper Front  
 Scratched  
 Over 100mm Thru Paint

4: Qtr Panel Moulding os  
 Scuffed (Unpainted)  
 Over 100mm

Interior

|                       |    |    |                       |    |    |
|-----------------------|----|----|-----------------------|----|----|
| Carpet Condition      |    | OK | Upholstery Condition  |    | OK |
| Seat Condition        |    | OK | Odour                 |    | -  |
| Engine Runs           | OK |    | No Excessive Smoking  | OK |    |
| EML light illuminated | OK |    | DPF light illuminated | OK |    |
| ABS light illuminated | OK |    |                       |    |    |