

VEHICLE INSPECTION REPORT

MX69EHF

Iveco Daily 72-180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Avonmouth

Reg. date 23/01/2020

Year 2020

Mileage 191,442 Km Not Warranted

Fuel Type DIESEL

GVW 7200kg

Colour BLUE

VIN ZCFC670D80D648128

Body Style Car Transporter

MOT Due 28/02/2027

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Steel

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Digital radio
- Front electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door osf
Scratched
Over 25mm Thru Paint



3: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition		Poor	Upholstery Condition		OK
Seat Condition		OK	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
Brakes		OK			
Parking Brake		OK			
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK