

VEHICLE INSPECTION REPORT

MK21EOZ

Man TGX 26.470

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	44000kg	Cab Type	GM CAB
Reg. date	01/03/2021	Colour	WHITE	Gearbox	AUTOMATIC
Year	2021	VIN	WMA23KZZ4MP155745	Axle Combi	6x2
Mileage	602,236 Km Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Fuel Type	DIESEL	MOT Due	31/12/2026	Rear Suspension	Air

SLIDING 5TH WHEEL, BEEN ON MAN R&M CONTRACT

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos




1: Door osf
Scratched
Over 25mm Thru Paint

2: Panel Front
Scratched
Over 25mm Thru Paint



3: Bonnet
Cracked
Replace

4: Bumper Front
Chipped
Multiple Chips



5: Qtr Panel Trim ns
Broken
Replace

6: Qtr Panel osr
Dented
Over 30mm



7: Screen Front
Chipped
Over 10mm

8: Door Pad osf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		