

VEHICLE INSPECTION REPORT

WO72JXE

Ford Transit 350 2.0 EcoBlue 130ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location Doncaster

Reg. date 28/02/2023

Year 2023

Mileage 75,872 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN WF0EXXTTRENS74357

Body Style Panel Van L3

MOT Due 27/02/2027

CAP Clean £10,550.00

CAP Average £9,800.00

CAP Below £8,450.00

Gearbox MANUAL

Gears 6

AD-BLUE

Tyres

NSF

NSR

OSF


OSR






Spare

Features

- Bluetooth connection
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Not Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Missing
Replace

4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Qtr Panel nsr
Dented
Over 30mm

6: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

10: Screen Front
Chipped
Over 10mm



11: Seat Base Cover osf
Holed
Over 3mm

12: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition
Seat Condition

OK
Poor

Upholstery Condition
Odour

OK
No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		