

VEHICLE INSPECTION REPORT

KR69RXG

Scania S 500

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location	Doncaster	GVW	44000kg	Cab Type	HIGHLINE CAB
Reg. date	03/02/2020	Colour	WHITE	Gearbox	AUTOMATIC
Year	2020	VIN	YS2S6X20009264944	Axle Combi	6x2
Mileage	753,451 Km Not Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Fuel Type	DIESEL	MOT Due	31/12/2026	Rear Suspension	Air

SINGLE LINE PTO HYDRAULICS Copy of V5 Available

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Bluetooth connection
- Digital radio
- Leather seat trim
- Cruise control
- Air conditioning
- Navigation system
- Front electric windows
- Auxiliary input socket
- Central locking


Photos







Condition Check



Damage Photos



1: Other
N/A
N/A

2: Bonnet
Chipped
Multiple Chips



3: Panel Front
Dented
Over 30mm

4: Panel Front
Dented
With Paint Damage



5: Bumper Front Moulding
Broken
Replace

6: Bonnet
Dented
With Paint Damage



7: Bumper Front Moulding
Missing
Replace

8: Bumper Front Moulding
Missing
Replace



9: Bumper Front Moulding
Broken
Replace

10: Door nsf
Dented
Over 30mm



11: Qtr Panel nsr
Dented
Over 30mm

12: Qtr Panel Trim ns
Broken
Replace



13: Door osf
Dented
Over 30mm

14: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		