

VEHICLE INSPECTION REPORT

K54281

KOMATSU PC210-8LC

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2012	Fuel Type	Diesel	Body Style	Excavator
Year	2012	Colour		Gearbox	Hydrostatic
Mileage	9,247 Hours Not Warranted	VIN	KMTPC180T55K54281		

COLLECT FROM HALIFAX ROTATION PIPE WORK, HAMMER PIPEWORK, HYDRAULIC QUICK HITCH

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





