

VEHICLE INSPECTION REPORT

YK68WLD

Volvo FH 500

Non Runner
Inspection

Serious Damage?		Vehicle	
	No	VAT	Plus VAT
		V5	N/A

Details

Location	Doncaster	GVW	44000kg	Cab Type	GLOBETROTTER CAB
Reg. date	08/10/2018	Colour	WHITE	Gearbox	AUTOMATIC
Year	2018	VIN	YV2RT40CXJB881432	Axle Combi	6x2
Mileage	Not Showing	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Fuel Type	Diesel	Service history	None	Rear Suspension	Air

NON RUNNER - WILL NOT POWER UP, BRAKES WOUND OFF SLIDING 5TH WHEEL, MOT SHOWS 535,466 KM 07/10/2024

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Door nsf
Dented
Over 30mm

4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel Trim os
Missing
Replace

6: Door Mirror Assy osf
Broken
Replace




7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint

8: Carpets Front
Holed
Over 3mm



9: Seat Base Cover osf
Holed
Over 3mm



10: Seat Base Cover nsf
Soiled
Heavy



11: Fascia Panel
Missing
Replace

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs		Fault	