

VEHICLE INSPECTION REPORT

100899

KOMATSU D155AX-8EO

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Customer Premises	Mileage	486 Hours Warranted	VIN	KMT0D126KSC100899
Reg. date	01/01/2026	Fuel Type	DIESEL	Body Style	DOZER
Year	2026	Colour	YELLOW	Gearbox	HYDROSTATIC

LOCATION SHOTTS, SCOTLAND, 24HRS NOTICE REQUIRED FOR COLLECTION 710MM STEEL TRACK PADS, A/C, PREMIUM SEAT, SURROUND CAMERA SYSTEM, KOMTRAX SATELLITE MONITORING SYSTEM, DUAL TILT SPEC, VARIABLE GIANT RIPPER C/W SUPER HARD BIT AND EDGE, GROUNDVELD AUTO LUBE SYSTEM.

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



