

VEHICLE INSPECTION REPORT

PN21FGP

SCANIA R 450

Cat: S **Incident History**
Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Location	Bedford	GVW	44000kg	Cab Type	HIGHLINE CAB
Reg. date	01/05/2021	Colour	WHITE	Gearbox	AUTOMATIC
Year	2021	VIN	YS2R6X20005617289	Axle Combi	6x2
Mileage	326,779 Km Warranted	Body Style	Tractor Unit	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	31/05/2027		

CATEGORY S INSURANCE LOSS. VEHICLE STRUCTURALLY DAMAGED BUT REPAIRABLE - INSURER DECIDED NOT TO REPAIR FRIDGE, REAR LIFT, TAG AXLE

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Air conditioning
- Leather seat trim

Photos





