

VEHICLE INSPECTION REPORT

SG19XKW

JCB 535-125 HI-VIS

Inspection

Vehicle

VAT	Plus VAT
V5	Photocopy

Details

Location	Doncaster	Fuel Type	DIESEL	Gearbox	Auto
Reg. date	02/04/2019	Colour	YELLOW	Axle Combi	4x4
Year	2019	VIN	JCB5ANAGCK2787107		
Mileage	4,295 Hours Not Warranted	Body Style	Telehandler		

FAULT LIGHT ON DASH P049E.00

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





