

VEHICLE INSPECTION REPORT

Q682VKE

HAMM HD10C

Imported
Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Bedford	Mileage	1,158 Hours Not Warranted	VIN	H1993077
Reg. date	01/12/2019			Body Style	Roller
Year	2019	Fuel Type	DIESEL		
		Colour	WHITE/GREY		

Tyres

NSF
NSR
OSF
OSR
Spare

Photos



