

VEHICLE INSPECTION REPORT

SF17CBX

Ford Tourneo Custom 310 2.0 TDCI 105PS ZETEC

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 08/03/2017

Year 2017

Mileage 151,622 Miles
Warranted

Fuel Type DIESEL

Colour SILVER

VIN WF03XXTTG3GS20928

Body Style Ambulance

MOT Due 20/07/2027

CAP Clean £4,300.00

CAP Average £3,600.00

CAP Below £2,700.00

Gearbox MANUAL

Gears 6

Doors 5

AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS, WHEELCHAIR RAMP

Tyres

NSF

NSR

OSF

OSR






Spare

Features

- Bluetooth connection
- Air conditioning
- Passenger airbag
- Cruise control
- Front electric windows
- Central locking
- Park assist camera
- Metallic Paint
- Cloth seat trim
- Digital radio
- Drivers airbag


Photos







Condition Check



Damage Photos



1: B Post os
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Door nsr
Dented
Over 30mm



5: Door osr
Dented
With Paint Damage



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint

7: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		