

VEHICLE INSPECTION REPORT

FP70WJM

Daf XF 480

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location	Bedford	GVW	44000kg	Cab Type	SUPER SPACE CAB
Reg. date	17/01/2021	Colour	WHITE	Gearbox	AUTOMATIC
Year	2021	VIN	XLRTGH4300G332460	Axle Combi	4x2
Mileage	551,475 Km Not Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Fuel Type	Diesel	MOT Due	28/02/2027	Rear Suspension	Air

WARNING LIGHTS ON DASH SURROUND CAMERA SYSTEM

Tyres








NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4



Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Screen Front
Cracked
Replace

2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

4: Qtr Panel Moulding ns
Missing
Replace



5: Qtr Panel osr
Cracked
Replace

6: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



7: Centre Console Front
Missing
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK