

VEHICLE INSPECTION REPORT

C439688

CARTWRIGHT CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2016	Colour	BLUE	Axle Combi	Tri
Year	2016	VIN	SMWCS39DFGA160560	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer		
Fuel Type		Brakes	Drum		

LOCATION UDDINGSTON, SCOTLAND, 24HRS NOTICE REQUIRED FOR COLLECTION FERRY LASHING RINGS, GIGANT AXLES.

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



