

VEHICLE INSPECTION REPORT

FP68KYB

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Doncaster

Reg. date 07/01/2019

Year 2019

Mileage 494,444 Km Not Warranted

Fuel Type DIESEL

GVW 32000kg

Colour WHITE

VIN XLRADM4100G238925

Body Style Tipper

MOT Due 28/02/2027

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 8x4

Rear Suspension Steel

ALLOY BODY, EDBRO TIPPING GEAR, WEIGH SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4

Features

- Bluetooth connection
- Auxiliary input socket
- Front electric windows
- Cruise control
- Digital radio
- Central locking
- Navigation system
- Radio/CD
- Cloth seat trim
- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Panel Front
 Scratched
 Over 25mm Thru Paint

4: Bumper Front
 Scratched
 Over 100mm Thru Paint



5: Door osf
 Chipped
 Multiple Chips

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		