

VEHICLE INSPECTION REPORT

DG670SA

Man TGS 26.360

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	26000kg	Cab Type	DAY CAB
Reg. date	14/11/2017	Colour	BLUE	Gearbox	AUTOMATIC
Year	2017	VIN	WMA18SZZ2JM759367	Axle Combi	6x2
Mileage	285,233 Km Warranted	Body Style	Dropside & Crane	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	30/04/2027		

HMF 1420K REMOTE CRANE (YEAR 2017), SERVICE SCHEDULE LIST AVAILABLE

Tyres






NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Digital radio
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Door osf
Scratched
Over 25mm Thru Paint



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Bonnet
Chipped
Multiple Chips



5: Panel Front
Scratched
Over 25mm Thru Paint

6: Door nsf
Dented
Over 30mm



7: Wing nsf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		