

VEHICLE INSPECTION REPORT

YH18ZXN

Mercedes-Benz X Class 250d 4Matic Power

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

Details

Location	Bedford	GVW	3300kg	CAP Clean	£16,050.00
Reg. date	31/08/2018	Colour	BLACK	CAP Average	£13,600.00
Year	2018	VIN	WDF4702312G009716	CAP Below	£10,350.00
Mileage	82,434 Miles Not Warranted	Body Style	Pickup Double Cab	Gearbox	AUTOMATIC
Fuel Type	DIESEL	MOT Due	04/11/2026	Gears	7

OUTSTANDING RECALL, TOW BAR, E/MIRRORS, AD-BLUE

Tyres

NSF

NSR

OSF



OSR




Spare

Features

- Front parking sensor
- Digital radio
- Leather seat trim
- Navigation system
- Air conditioning
- Park assist camera
- Front electric windows
- Rear parking sensor
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
Chipped
Multiple Chips



5: Door nsr
Scratched
UpTo 25mm Thru Paint

4: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Not Thru Paint



6: Qtr Panel Arch Extension ns
Scratched (Painted)
UpTo 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK