

VEHICLE INSPECTION REPORT

DA21GXJ

Man TGL 12.220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Doncaster

Reg. date 14/06/2021

Year 2021

Mileage 509,359 Km Warranted

Fuel Type DIESEL

GVW 12000kg

Colour YELLOW

VIN WMA14DZZ4MY430187

Body Style Tilt & Slide

MOT Due 28/02/2027

Cab Type CREW CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Air

BONIFACE 5TVLA + SCL DEMOUNT BODY, SPEC LIFT, SLIDING WINCH, DYNA CYCLE, 3 POINT SEAT BELTS, UNDERSEAT STORAGE

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bumper Front
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Cracked
Over 25mm

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm

6: Door osf
Dented
With Paint Damage

Interior

Carpet Condition
Seat Condition

-
-

Upholstery Condition
Odour

-
-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		