

VEHICLE INSPECTION REPORT

BN70XWM

Ford Transit Connect 200 1.5 EcoBlue 120ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 10/12/2020

Year 2020

Mileage 32,644 Miles Not Warranted

Fuel Type DIESEL

GVW 2245kg

Colour GREY

VIN WF0RXXWPGRLY85057

Body Style Panel Van L1

CAP Clean £8,975.00

CAP Average £7,850.00

CAP Below £6,300.00

Gearbox MANUAL

Gears 6

AD BLUE, SIDE LOAD DOOR, ROOF RACK, E/MIRRORS, HEATED WINDSCREEN, ALLOY WHEELS

Tyres

NSF

NSR

OSF


OSR


Spare

Features

- Bluetooth connection
- Digital radio
- Drivers airbag
- Cruise control
- USB/iPod interface
- Central locking
- Heated front seat
- Air conditioning
- Cloth seat trim
- Rear parking sensor
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
UpTo 25mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Door nsf
Chipped
Multiple Chips



5: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Scratched
25 to 100mm Thru Paint

10: Door osr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Dented
Over 30mm

12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Chipped
1 To 5

14: Door osf
Dented
Over 30mm



15: Door osf
Dented
Over 30mm

16: Wing osf
Scratched
Over 25mm Thru Paint



17: Bumper Front
Scratched
Over 100mm Thru Paint

18: Seat Base Cover osf
Missing
Replace

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Gearbox Static Gear Selection (engine running)	OK	
Turbo Boosting	OK		No Excessive Smoking	OK	
Parking Brake	OK				
EML light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK				