

# VEHICLE INSPECTION REPORT

**DX70TFZ**

## Daf LF 180

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Location Avonmouth

Colour WHITE

Axle Combi 4x2

Reg. date 26/11/2020

VIN XLRAEL1500L495107

Rear Suspension Steel

Year 2020

Body Style Box Van

Rear Doors Roller

Mileage 153,011 Km Warranted

MOT Due 30/04/2027

Tail Lift Column

Fuel Type DIESEL

Cab Type DAY CAB

GVW 7500kg

Gearbox MANUAL

\*WARNING LIGHT ON DASH\*

### Tyres


NSF NSI1 NSI2 NSI3 NSI4


OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4

OSO1 OSO2 OSO3 OSO4


### Photos







## Condition Check



## Damage Photos



1: Wing osf  
Scratched  
Over 25mm Not Thru Paint

2: Screen Front  
Chipped  
UpTo 10mm



3: Bumper Front  
Chipped  
Multiple Chips

4: Bumper Front  
Scratched  
25 to 100mm Thru Paint



5: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm

6: Wing Front Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm



7: Door Pad nsf  
Broken  
Replace

8: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint





9: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

10: Wing Front Arch Extension os  
Scuffed (Unpainted)  
Over 100mm



11: Door Mirror Assy osf  
Scuffed (Unpainted)  
UpTo 100mm

12: Door osf  
Scratched  
UpTo 25mm Not Thru Paint



13: Door osf  
Chipped  
Edge Chip

## Interior

| Carpet Condition         |    | Average | Upholstery Condition                           |    | Average |
|--------------------------|----|---------|------------------------------------------------|----|---------|
| Seat Condition           |    | Average | Odour                                          |    | -       |
| Engine Runs              | OK |         | Gearbox 1st and Reverse Test                   | OK |         |
| Brakes                   | OK |         | Clutch Slip Test from Static                   | OK |         |
| Parking Brake            | OK |         | Gearbox Static Gear Selection (engine running) | OK |         |
|                          |    |         | No Excessive Smoking                           | OK |         |
| EML light illuminated    | OK |         | Oil warning light illuminated                  | OK |         |
| Airbag light illuminated | OK |         | DPF light illuminated                          | OK |         |
| ABS light illuminated    | OK |         | Service indicator light illuminated            | OK |         |