

VEHICLE INSPECTION REPORT

PF18YFM

Fiat Doblo 1.3 MULTIJET 16V 95PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location	Bedford	GVW	2020kg	CAP Clean	£1,875.00
Reg. date	21/08/2018	Colour	WHITE	CAP Average	£1,600.00
Year	2018	VIN	ZFA26300006L14159	CAP Below	£1,225.00
Mileage	141,092 Miles Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	20/08/2027	Gears	5

SIDE LOADING DOOR, TOW BAR

Tyres

NSF

NSR

OSF


OSR



Spare

Features


- Front electric windows

Photos






Condition Check



Damage Photos



1: Bumper Front
Cracked
Over 25mm



2: Bonnet
Dented
Over 2 UpTo 10mm



3: Bonnet
Chipped
Multiple Chips

4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Door Mirror Glass os
Broken
Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK