

# VEHICLE INSPECTION REPORT

**SR19HDZ**

## Ford Transit 350 2.0 TDCi 130ps H2

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Location Livingston

Reg. date 24/04/2019

Year 2019

Mileage 94,589 Miles  
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN WF0XXXTTGXKC37897

Body Style Panel Van

Service history Full

Service documents Printout

Last service date 23/04/2026

Last service miles 89,947

MOT Due 25/04/2027

CAP Clean £5,675.00

CAP Average £4,875.00

CAP Below £3,800.00

Gearbox MANUAL

Gears 6

### Tyres

NSF

NSR




OSF

OSR


Spare

### Photos





## Condition Check



## Damage Photos



1: Seat Base Cover of  
Holed  
Over 3mm

2: Bonnet  
Dented  
Over 30mm



3: Door osf  
Dented  
Over 30mm

4: Qtr Panel osr  
Dented  
Over 30mm

Interior

|                          |    |                                                |    |
|--------------------------|----|------------------------------------------------|----|
| Carpet Condition         | OK | Upholstery Condition                           | OK |
| Seat Condition           | OK | Odour                                          | No |
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Turbo Boosting           | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake            | OK | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | DPF light illuminated                          | OK |
| ABS light illuminated    | OK | Service indicator light illuminated            | OK |
| Windows                  | OK | Radio                                          | OK |
|                          |    | Steering                                       | OK |