

VEHICLE INSPECTION REPORT

FL75EVP

Ford Transit 350 2.0 EcoBlue 130ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	08/09/2025	Colour	WHITE	CAP Average	£20,850.00
Year	2025	VIN	WF0CXXTTTRCSR08273	CAP Below	£18,400.00
Mileage	19,734 Miles Not Warranted	Body Style	Tipper Double Cab	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	07/09/2028	Gears	6
GVW	3500kg	CAP Clean	£22,100.00		

OUTSTANDING RECALL, TIPPER INOP, REAR SEAT BELTS DISASSEMBLED AD BLUE, TOW BAR

Tyres

NSF

NSR

OSF



OSR





Spare

Features

- Bluetooth connection
- Air conditioning
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Front parking sensor
- Drivers airbag
- Mobile phone App interface
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Screen Front
Cracked
Replace



2: Bonnet
Chipped
Multiple Chips



3: Wing nsf
Dented
With Paint Damage

4: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



5: Door nsf
Chipped
Multiple Chips

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Dented
With Paint Damage

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Lamp nsr
Broken
Replace

10: Lamp osr
Broken
Replace



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint

12: Sill Panel Trim os
Missing
Replace



13: Door osf
Chipped
Multiple Chips

14: Door osf
Scratched
Over 25mm Thru Paint




15: Wing osf
Scratched
Over 25mm Thru Paint

16: Wing osf
Scratched
Over 25mm Thru Paint



17: Bumper Front
Scratched
Over 100mm Thru Paint

18: Seat Base Cover nsf
Torn
Over 3mm



19: Dash Warning Lights
Displayed
No Action

20: Fascia Panel
Broken
Replace




21: Seat Belt nsr
Broken
Replace

22: Seat Belt osr
Broken
Replace



23: Seat Base Cover osr
Missing
Replace

24: Door Pad osr
Broken
Replace



25: Door Pad nsr
Broken
Replace

26: Seat Base Cover nsr
Missing
Replace

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		