

VEHICLE INSPECTION REPORT

PF64WDT

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	VIN	XLRAEL1500L442290	Cab Type	DAY CAB
Reg. date	27/02/2015	Body Style	Box Van	Gearbox	MANUAL
Year	2015	Service history	Yes	Axle Combi	4x2
Mileage	817,423 Km Warranted	Service documents	Printout	Rear Suspension	Steel
Fuel Type	HVO	Last service date	28/07/2025	Tail Lift	Cantilever
GVW	7500kg	Last service miles	729,873		
Colour	RED	MOT Due	31/10/2026		

FUELLED BY HYDROTREATED VEGETABLE OIL


Tyres






NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bonnet
Chipped
Multiple Chips

4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Door osf
Scratched
Over 25mm Thru Paint

6: Door osf
Scratched
Over 25mm Thru Paint



7: Door Pad nsf
Soiled
Heavy

8: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		