

# VEHICLE INSPECTION REPORT

**LK66YZG**

## ISUZU N75.190

### Inspection

### Vehicle

|     |           |
|-----|-----------|
| VAT | Plus VAT  |
| V5  | To Follow |

### Details

|           |                          |            |                   |                 |           |
|-----------|--------------------------|------------|-------------------|-----------------|-----------|
| Location  | Livingston               | GVW        | 7500kg            | Gearbox         | AUTOMATIC |
| Reg. date | 28/09/2016               | Colour     | WHITE             | Axle Combi      | 4x2       |
| Year      | 2016                     | VIN        | JAANPR75MF7101377 | Rear Suspension | Steel     |
| Mileage   | 459,296 Km Not Warranted | Body Style | Fridge Box        | Rear Doors      | Barn      |
| Fuel Type | DIESEL                   | Cab Type   | DAY CAB           | Tail Lift       | Column    |

\*WARNING LIGHT ON DASH, NO POWER STEERING\* CARRIER XARIOS 600 UNIT, STANDBY PLUG.

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Radio/CD

## Photos





