

VEHICLE INSPECTION REPORT

CP62PXR

Ford Ranger XL 2.2 TDCi 150 4WD

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 30/01/2013

Year 2013

Mileage 109,768 Miles Not Warranted

Fuel Type DIESEL

GVW 3200kg

Colour SILVER

VIN 6FPGXXMJ2GCS76830

Body Style Pickup Double Cab

MOT Due Expired

CAP Clean £2,875.00

CAP Average £2,250.00

CAP Below £1,500.00

Gearbox MANUAL

Gears 6

Axle Combi 4x4

TOW BAR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Radio/CD
- Passenger airbag
- Air conditioning
- Central locking
- Front electric windows
- Cloth seat trim
- Drivers airbag

Photos





Condition Check




Damage Photos





1: Bonnet
Scratched
Rusted

2: Wing nsf
Chipped
Multiple Chips



3: Door nsf
Scratched
Over 25mm Thru Paint

4: Door nsf
Dented
With Paint Damage



5: Qtr Panel nsr
Dented
With Paint Damage

6: Qtr Panel nsr
Chipped
Multiple Chips



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Tailgate
Dented
Over 30mm

10: Panel Rear
Poor Previous Repair
Paint Flake





11: Qtr Panel osr
Scratched
Over 25mm Thru Paint

12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Door osf
Dented
Over 30mm

14: Door osf
Chipped
Multiple Chips





15: Door osf
 Scratched
 Over 25mm Thru Paint

16: Wing osf
 Scratched
 Over 25mm Thru Paint



17: Fascia Trim
 Damaged
 Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			