

VEHICLE INSPECTION REPORT

BU69TSX

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	05/12/2019	Colour	WHITE	Gearbox	MANUAL
Year	2019	VIN	XLRAEL3700L491301	Axle Combi	4x2
Mileage	380,193 Km Warranted	Body Style	Fridge Box	Rear Suspension	Air
Fuel Type	DIESEL	Service history	None	Rear Doors	Roller
GVW	18000kg	Cab Type	DAY CAB	Tail Lift	Tuckaway

ALTERNATOR ISSUES - ONLY RUNS WITH BOOST PACK, WARNING LIGHTS, THERMOKING T-1000R, STANDBY PLUG


Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Radio/CD
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint

2: Bonnet
Chipped
Multiple Chips



3: Panel Front
Scratched
Over 25mm Thru Paint

4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Qtr Panel osr
Cracked
Replace



7: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	Fault		