

VEHICLE INSPECTION REPORT

SC17DBU

Renault Master LL35 2.3 dCi 130PS BUSINESS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Livingston

Reg. date 23/05/2017

Year 2017

Mileage 82,988 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN VF1VB000756524040

Body Style Tipper Double Cab

MOT Due 10/08/2027

CAP Clean £6,850.00

CAP Average £5,700.00

CAP Below £4,225.00

Gearbox MANUAL

Gears 6

Axle Combi 4x2

TOW BAR

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover nsf
Torn
Over 3mm

2: Seat Base Cover osf
Torn
Over 3mm



3: Carpets Front
Torn
Over 10mm

4: Sill os
Rusted
Over 5mm



5: Bonnet
Dented
With Paint Damage

6: Wing osf
Dented
With Paint Damage



7: Door osf
Dented
With Paint Damage

8: B Post os
Dented
Over 30mm



9: Qtr Panel osr
Dented
With Paint Damage

10: Tailgate
Rusted
Over 5mm



11: Qtr Panel nsr
Dented
With Paint Damage

12: Sill ns
Dented
With Paint Damage



13: D Post ns
Dented
Over 30mm

14: Door nsf
Dented
With Paint Damage



15: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Poor		Odour		No	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		
Windows	OK			Radio	OK		
				Steering	OK		