

VEHICLE INSPECTION REPORT

SC17DCV

Renault Master LL35 2.3 dCi 130PS BUSINESS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Livingston

Colour BLUE

CAP Below £4,075.00

Reg. date 12/05/2017

VIN VF1VB000856524046

Gearbox MANUAL

Year 2017

Body Style Tipper Double Cab

Gears 6

Mileage 88,558 Miles
Warranted

MOT Due 11/08/2027

Axle Combi 4x2

Fuel Type DIESEL

CAP Clean £6,625.00

GVW 3500kg

CAP Average £5,500.00

WARNING LIGHTS ON DASH, TOW BAR

Tyres

NSF


NSR


OSF

OSR


Spare

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm

2: Carpets Front
Torn
Over 10mm



3: Seat Base Cover nsr
Torn
Over 3mm

4: Bonnet
Dented
With Paint Damage



5: Wing osf
Dented
With Paint Damage

6: Door osf
Dented
With Paint Damage



7: Sill os
Dented
With Paint Damage

8: Door osr
Dented
Over 30mm



9: Qtr Panel osr
Dented
With Paint Damage




10: Tailgate
Hole
Over 10mm



11: Qtr Panel nsr
Dented
With Paint Damage



12: Door nsr
Rusted
Over 5mm



13: D Post ns
Rusted
Over 5mm



14: Sill ns
Dented
With Paint Damage

No Image



15: Door nsf
Dented
With Paint Damage



16: Wing nsf
Dented
With Paint Damage

17: Handle Outer nsr
Broken
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault

Windows

OK

Radio

OK

Steering

OK