

VEHICLE INSPECTION REPORT

SC17RNE

Renault Master LL35 2.3 dCi 130PS BUSINESS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Livingston

Reg. date 25/05/2017

Year 2017

Mileage 72,116 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour BLUE

VIN VF1VB000456524044

Body Style Tipper Double Cab

MOT Due 25/05/2027

CAP Clean £7,300.00

CAP Average £6,075.00

CAP Below £4,500.00

Gearbox MANUAL

Gears 6

Axle Combi 4x2

TOW BAR

Tyres

NSF

NSR

OSF

OSR



Spare

Features


- Front electric windows
- Drivers airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm

2: Carpets Front
Torn
Over 10mm



3: Sill os
Rusted
Over 5mm

4: Bonnet
Dented
Over 30mm



5: Wing nsf
Dented
Over 30mm

6: Door osf
Dented
Over 30mm



7: Door osr
Dented
With Paint Damage

8: Sill os
Dented
With Paint Damage



9: Qtr Panel osr
Dented
With Paint Damage

10: Tailgate
Dented
With Paint Damage



11: Qtr Panel nsr
Dented
With Paint Damage

12: Door nsr
Dented
With Paint Damage



13: D Post ns
Dented
With Paint Damage

14: Sill ns
Dented
With Paint Damage



15: Door nsf
Dented
With Paint Damage

16: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition	Average		Upholstery Condition	Average	
Seat Condition	Average		Odour	No	
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK