

VEHICLE INSPECTION REPORT

SC17PZK

Peugeot Bipper 1.3 HDi 80PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 24/05/2017

Year 2017

Mileage 31,534 Miles
Warranted

Fuel Type DIESEL

GVW 1750kg

Colour BLUE

VIN VF3AAFHY6H8878422

Body Style Panel Van SWB

MOT Due 09/06/2027

CAP Clean £2,250.00

CAP Average £1,850.00

CAP Below £1,375.00

Gearbox MANUAL

Gears 5

Axle Combi 4x2

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Rear parking sensor

Photos





Condition Check



Damage Photos



1: Sill os
Scratched
Over 25mm Not Thru Paint

2: Bonnet
Dented
Over 30mm



3: Tailgate
Dented
Over 30mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK