

VEHICLE INSPECTION REPORT

SC17ASX

Renault Master LL35 2.3 DCI 130PS BUSINESS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 22/05/2017

Year 2017

Mileage 52,779 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN VF1VB000056524025

Body Style Tipper Double Cab

MOT Due 10/08/2027

CAP Clean £8,050.00

CAP Average £6,725.00

CAP Below £4,975.00

Gearbox MANUAL

Gears 6

Axle Combi 4x2

Steering Combi Steer

Rear Suspension Steel

TOW BAR

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Front electric windows
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm

2: Seat Base Cover nsf
Torn
Over 3mm



3: Sill os
Scratched
Over 25mm Thru Paint

4: Bonnet
Dented
2 Or Less UpTo 10mm



5: Wing osf
Dented
2 Or Less UpTo 10mm

6: Door osf
Rusted
Over 5mm



7: Door osr
Dented
Over 30mm

8: Qtr Panel osr
Dented
With Paint Damage



9: Qtr Panel nsr
Rusted
Over 5mm



10: Door nsr
Dented
With Paint Damage



11: Door nsf
Dented
Over 30mm

12: Sill ns
Dented
With Paint Damage

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Poor		Odour		No	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		

Windows

OK

Radio

OK

Steering

OK