

VEHICLE INSPECTION REPORT

FN18BCU

SCANIA R 520

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Location	Doncaster	Colour	WHITE	Gearbox	AUTOMATIC
Reg. date	11/05/2018	VIN	YS2R6X20009235227	Axle Combi	6x2
Year	2018	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	662,436 Km Not Warranted	Service history	None	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	28/02/2027		
GVW	44000kg	Cab Type	HIGHLINE CAB		

INFOTAINMENT SCREEN INOPERATIVE, SERVICE HISTORY AVAILABLE

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Digital radio
- Air conditioning

Photos





