

VEHICLE INSPECTION REPORT

HN69VYU

Skoda Kodiaq 2.0 TDI SE

Inspection

Serious Damage? No

Vehicle

VAT	VAT Qualifying
V5	Present
Cap Id	77504
Cap Code	SKKO207SE5EDTM4

Details

Location	Bedford	Colour	SILVER	CAP Below	£11,700.00
Reg. date	17/02/2020	VIN	TMBMJ7NS3L8510219	Gearbox	MANUAL
Year	2020	Body Style	Estate	Gears	6
Mileage	23,927 Miles Warranted	MOT Due	16/11/2026	Doors	5
Fuel Type	DIESEL	CAP Clean	£14,250.00	Axle Combi	4x4
GVW	2443kg	CAP Average	£13,000.00		

EX-FIRE SERVICE CONTRACT - BLUE LIGHTS REMOVED KEYLESS IGNITION, E/MIRRORS

Tyres



NSF
NSR
OSF
OSR
Spare




Features

- Rear parking sensor
- Radio/CD
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear electric windows
- Alloy wheels


Photos







Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint



3: Door nsr
Dented
Between 10mm + 30mm

4: Tailgate
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK